





FIG. 1



PRIOR ART

2/18

FIG. 2



3/18

306 RESIST PATTERN FOR 1st WIRING LINE




FIG. 3A

307 TRENCH FOR 1st WIRING LINE




FIG. 3B

4/18




FIG. 3C




FIG. 3D

5/18




FIG. 3E




FIG. 3F

6/18




FIG. 3G

7/18




FIG. 3H

8/18

328 1st CONDUCTOR PLUG




FIG. 3I




FIG. 3J

9/18

320 RESIST PATTERN FOR 2nd WIRING LINE




FIG. 3K

10/18




FIG. 3L

11/18




FIG. 3M

12/18




FIG. 3N

13/18





FIG. 30


14/18

FIG. 4




15/18

FIG. 5




16/18

FIG. 6



17/18

FIG. 7



18/18

FIG. 8

